

## Misrepresentation of Intertek Certified Product / Représentation erronée du produit certifié Intertek

### MR. STEAK four and five burner gas patio grills

Notification Type:	Safety / Sécurité
Certification Type:	Not Intertek Certified

#### Notification

Intertek notifies consumers, retailers and distributors that we have been notified by the applicant that the products identified below have been misrepresented as Intertek Certified. / Intertek informe les consommateurs, les détaillants et les distributeurs que nous avons été avisés par le demandeur que les produits identifiés ci-dessous ont été mal représentés comme étant certifiés Intertek.

#### Company Identification

Ningbo Huige Outdoor Products Co Ltd

#### Product Identification

MR. STEAK Models MS-4B-PG and MS-5B-PG four and five burner models of MR. STEAK propane gas grills, models MS-4B-PG, SKU 2472264 and MS-5B-PG, SKU 2472265, that have both a fuel gauge and a fuel line that is not attached to the inside of the grill. Mr Steak is a **brand name is not associated to our global directory** Recall number: 20-038 see link to CPSC <https://www.cpsc.gov/Recalls/2020/Bass-Pro-Recalls-MR-STEAK-Gas-Grills-Due-to-Fire-Hazard>

#### Hazard Involved

The gas regulator hose with attached fuel gauge can melt if it comes in contact with the bottom of the grill's firebox, posing a fire hazard.

#### What To Do

Use should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers. / L'utilisation doit être immédiatement interrompue et revenir au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.

Published: December 26, 2019  
Revised:

Public Notice ID: 2019-41  
Page 2 of 2

**Photos and Images**



MR. STEAK four burner model, MS-4B-PG