

## Misrepresentation of Intertek Certified Product / Représentation erronée du produit certifié Intertek

### Owens Corning - ProArmor Synthetic Roofing Underlayment

Notification Type:	Misuse of Certification Mark / Mauvaise utilisation des marques de certification
Certification Type:	ETL Listed - US and Canada

#### **Notification**

Intertek notifies consumers, retailers and distributors that we have been notified by the applicant that the products identified below have been mislabeled and therefore misrepresented as to the status of their Intertek certification. / Intertek informe les consommateurs, les détaillants et les distributeurs que nous avons été informés par le demandeur que les produits identifiés ci-dessous ont été mal étiquetés et donc faussés quant au statut de leur certification Intertek.

#### **Company Identification**

Owens Corning

#### **Product Identification**

A mislabeling and misrepresentation of ETL-certified product Owens Corning, ProArmor Synthetic Underlayment. The product was tested for the US market, however, the nameplate and ETLus certification mark incorrectly include two control numbers (5007136 and 5007225). As there are two control numbers, the manufacturing factory cannot be identified related to the ETLus certification.

Additionally, the product label also includes information in French which may create the impression that the product is also certified for the Canadian market.

Please refer to photo on page 2 for details.

#### **Hazard Involved**

The product has not been evaluated to the requirements for the Canadian market and is unknown if it complies with any Canadian requirements.

#### **What To Do**

Use should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers. / L'utilisation doit être immédiatement interrompue et revenir au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.



Total Quality. Assured.

545 E Algonquin Road, Suite H  
Arlington Heights, IL 60005 USA

Telephone: 847-439-5667  
**intertek.com**

Published: April 6, 2021  
Revised:

Public Notice ID: 2021-10  
Page 2 of 2

**Photos and Images**

