

Misrepresentation of Intertek Certified Product Labels

30, 60, 90 Min Fire Doors AND 30, 60, 90 min Door Assembly labels

Notification Type:	Misuse of Certification Mark
Certification Type:	Not Intertek Certified

Notification

Intertek notifies public that we have been notified by the applicant that the labels identified below have been misrepresented as Intertek Certified.

Company Identification

Form for Contracting & Decoration

Product Identification

A misrepresentation of certified product labels. Client has withdrawn their certification with outstanding labels that have not been returned to Intertek. Page 2 for label details.

Hazard Involved

Not Intertek Certified

What To Do

Use should be immediately discontinued and return to the point of purchase and the labels should be removed and returned to Intertek.

Published: July 24, 2025
Revised:

Public Notice ID: 2025-68
Page 2 of 2

Photos and Images

Company name:	Form for Contracting & Decoration					
Address	Plot 80 & 82, Industrial Zone, 11728 ZAHRAA EL-MAADI, EGYPT					
W/N:	20879	20880	20881	24081	24082	24083
Label Description:	Halspan 30 Mins FD	Halspan 60 Mins FD	Halspan 90 Mins FD	Halspan 90 Minute Fire Wood Door Assembly	Halspan 30 Minute Optima Fire Door Assembly	Halspan 60 Minute Optima Fire Wood Door Assembly
Quantity	301	28	4	25	275	200
Label #	35796 to 36096	34054 to 34081	9981 to 9984	1 to 25	1 to 275	1 to 200